








SWP - 05

HISTORY WITH A FUTURE

Protective Equipment	Stages Action - Brief description of what to do in the right order	Hazards Applicable to each stage.	Key Points How to do it - identify equipment, safety, quality and performance requirements.	Protective Equipment Required
1 	MAINTENANCE CHECKS	CUTS	Check that handles are secure. Check that there are no burrs along handles. Note: Any faults, attach "Out of Service Tag" and report it to Infrastructure Manager.	1 4 11 12
2  3  4 	USING DROPPER KNOCKER	CUTS STRAINS SPRAINS	Conduct Work Safe Check. Warm body by performing warm up and stretching exercises. Place cylinder of Dropper Knocker over head of dropper/stanchion. Stand dropper/stanchion in desired location in an upright position. Grasp handles on both sides of knocker, lifting and lowering arms, using controlled force to knock in to required depth. Where possible avoid over the shoulder reaching. If using for prolonged time periods take frequent rest breaks or rotate workers. Note: Any faults, attach "Out of Service Tag" and report it to Infrastructure Manager.	1 2 3 4 11 12
11 	AFTER USE CARE		Once task has been completed store in safe area.	
12 